

## Message Text

UNCLASSIFIED

PAGE 01 NIAMEY 03143 181600Z

42

ACTION FBO-08

INFO OCT-01 AF-05 ISO-00 A-01 /015 W  
----- 058353

P 181452Z SEP 74(5

FM AMEMBASSY NIAMEY

TO SECSTATE WASHDC PRIORITY 8883

UNCLAS SAMEY 3143

FOR FBO

E.O. 11652: N/A

TAGS: ABLD, NG

SUBJECT: PROPERTY NO. 01559-AMBASSADOR'S RESIDENCE: REPAIR OF  
HOT WATER SYSTEM

1. SINCE MAY AMBASSADOR'S RESIDENCE HAS BEEN PLAGUED BY VARIETY WATER PROBLEMS AND ONE WAY OR ANOTHER SUPPLY HAS BEEN TOTALLY INADEQUATE. LATEST DEVELOPMENT IS THAT DURING PAST SIX WEEKS HOT WATER SYSTEM HAS DEVELOPED TWO SERIOUS LEAKS IN WALLS AND UNDER FLOORING. FIRST LEAK DEVELOPED IN HALLWAY CONNECTING GROUND FLOOR GUEST BEDROOM WITH ENTRANCE FOYER. FLOOR IN CONNECTING HALLWAY IS EXTREMELY HOT INDICATING LARGE LEAK WITH ACCUMULATION OF HOT WATER UNDER FLOOR. SECOND LEAK HAS DEVELOPED SOMEWHERE BETWEEN BASE OF SMALL STAIRWELL LEADING TO UNDERGROUND UTILITY ROOM AND KITCHEN. WATER IS LEAKING RAPIDLY INTO STAIRWELL AND UTILITY ROOM AND PRELIMINARY PROBES INTO THE WALL HAVE FAILED TO REACH THE LEAK.

2. LEAKS IMPOSSIBLE TO REACH WITHOUT EXTENSIVE CUTTING AND THUS DAMAGE TO WALLS AND FLOORS SINCE THERE IS NO BASEMENT AND NO WATER PIPE ACCESS TUNNELS UNDER THE RESIDENCE. ORIGINAL PLANS CALLED FOR TUNNELS LIKE THOSE INSTALLED IN CHANCERY BUT THEY WERE OMITTED. LOCAL PLUMBING EXPERTS WHO ORIGINALLY INSTALLED HOT WATER SYSTEM HAVE AGREED THAT ONLY OPTION IS TO BEGIN BREAKING THROUGH FLOORING. THEY ALSO POINT OUT THAT WEAKNESS OF ORIGINAL WELDED COPPER PIPE UTILIZED IN RESIDENCE COULD RESULT IN UNCLASSIFIED

UNCLASSIFIED

PAGE 02 NIAMEY 03143 181600Z

REPEATED PROBLEMS OF THIS NATURE IN FUTURE. ADDITIONAL PROBLEMS ARE THAT TERRAZZO FLOORING CANNOT BE REPRODUCED LOCALLY SINCE MATCHING MARBLE IS NOT FOUND HERE, ITALIAN ARTISANS WHICH ORIGINALLY LAID FLOOR ARE GONE AND SOPHISTICATED MACHINERY REQUIRED IS NO LONGER AVAILABLE LOCALLY.

3. POST IS ALSO CONCERNED OVER POTENTIAL STRUCTURAL DAMAGE TO RESIDENCE IF DEEP EXCAVATION INTO WALLS AND FLOORING OF RESIDENCE MADE WITHOUT PREPARATION AND SUPERVISION BY QUALIFIED PERSONNEL.

4. POST HAS CONSULTED ALL LOCAL EXPERTS AND HAS REACHED POINT WHERE MAJOR DECISIONS REQUIRED WHICH LOCAL EXPERTS NOT IZT NOT COMPETENT TO MAKE. THEREFORE, POST URGENTLY REQUESTS DISPATCH BY FBO OF QUALIFIED ENGINEER TO NIAMEY TO MAKE ON-THE-SPOT ANALYSIS OF PORBLEM AND TO RECOMMEND REPAIRS, COUNTERMEASURES OF LARGE-SCALE CHANGES.HECK

UNCLASSIFIED

NNN

\*\*\* Current Handling Restrictions \*\*\* n/a

\*\*\* Current Classification \*\*\* UNCLASSIFIED

## Message Attributes

**Automatic Decaptioning:** X  
**Capture Date:** 01 JAN 1994  
**Channel Indicators:** n/a  
**Current Classification:** UNCLASSIFIED  
**Concepts:** n/a  
**Control Number:** n/a  
**Copy:** SINGLE  
**Draft Date:** 18 SEP 1974  
**Decaption Date:** 01 JAN 1960  
**Decaption Note:**  
**Disposition Action:** n/a  
**Disposition Approved on Date:**  
**Disposition Authority:** n/a  
**Disposition Case Number:** n/a  
**Disposition Comment:**  
**Disposition Date:** 01 JAN 1960  
**Disposition Event:**  
**Disposition History:** n/a  
**Disposition Reason:**  
**Disposition Remarks:**  
**Document Number:** 1974NIAMEY03143  
**Document Source:** CORE  
**Document Unique ID:** 00  
**Drafter:** n/a  
**Enclosure:** n/a  
**Executive Order:** n/a  
**Errors:** n/a  
**Film Number:** D740261-0836  
**From:** NIAMEY  
**Handling Restrictions:** n/a  
**Image Path:**  
**ISecure:** 1  
**Legacy Key:** link1974/newtext/t19740984/aaaahpzb.tel  
**Line Count:** 83  
**Locator:** TEXT ON MICROFILM, TEXT ON-LINE  
**Office:** ACTION FBO  
**Original Classification:** UNCLASSIFIED  
**Original Handling Restrictions:** n/a  
**Original Previous Classification:** n/a  
**Original Previous Handling Restrictions:** n/a  
**Page Count:** 2  
**Previous Channel Indicators:**  
**Previous Classification:** n/a  
**Previous Handling Restrictions:** n/a  
**Reference:** n/a  
**Review Action:** RELEASED, APPROVED  
**Review Authority:** martinjw  
**Review Comment:** n/a  
**Review Content Flags:**  
**Review Date:** 08 MAR 2002  
**Review Event:**  
**Review Exemptions:** n/a  
**Review History:** RELEASED <08 MAR 2002 by maustmc>; APPROVED <30 JAN 2003 by martinjw>  
**Review Markings:**

Declassified/Released  
US Department of State  
EO Systematic Review  
30 JUN 2005

**Review Media Identifier:**  
**Review Referrals:** n/a  
**Review Release Date:** n/a  
**Review Release Event:** n/a  
**Review Transfer Date:**  
**Review Withdrawn Fields:** n/a  
**Secure:** OPEN  
**Status:** <DBA CORRECTED> srp 971126  
**Subject:** PROPERTY NO. 01559-AMBASSADOR'S RESIDENCE: REPAIR OF HOT WATER SYSTEM  
**TAGS:** ABLD, NG  
**To:** STATE  
**Type:** TE  
**Markings:** Declassified/Released US Department of State EO Systematic Review 30 JUN 2005